



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
July 6

Repair Work

Devil's Slide (post mile 39.14)

- See 7/5/06 Update for complete summary.
- Level 'B' (lower level ocean side) – Drilling for tie backs continued using two rigs. 40 of 58 tie backs now installed.



Drilling at level B

- Level 'D' (upper level cliff side) – Drilling for tie backs continued. 9 of 33 now installed.



Drilling at level D

Retaining (micropile) Wall

- Drilling and driving steel piles continued today. The 4 inch diameter steel piles are filled with cement slurry after being driven into the ground.



Steel piles

Drill rig



Micro pile wall drilling